

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

BU356
East
1/2-1
0.587 mi.
3102 ft.

MANHOLE 1503
OCEAN PKWAY AND NEPTUNE AVENUE
BROOKLYN, NY

NY Spills **S107521884**
N/A

Site 1 of 2 in cluster BU

Relative:
Higher

SPILLS:

Actual:
7 ft.

Name: MANHOLE 1503
Address: OCEAN PKWAY AND NEPTUNE AVENUE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0511714 / 2006-06-14
Facility ID: 0511714

Facility Type: ER
DER Facility ID: 307957
Site ID: 357925
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2006-01-10
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2006-01-10
CID: 75
Water Affected: N/A
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-01-11
Spill Record Last Update: 2006-07-17
Spiller Name: ERT DESK
Spiller Company: CON EDISON MANHOLE 1503
Spiller Address: OCEAN PKWAY AND NEPTUNE A
Spiller Company: 999
Contact Name: ERT DESK'
DEC Memo: "06/14/06 - See e-docs for Con Ed report detailing cleanup and closure. 162484. 1/10/2006 11:05 HRS S. SFERRAZZA #85751 MECH A MTCE SVCS REPORTS FINDING APPROX 1 GAL OF UNKNOWN OIL ON APPROX 20 GALS OF WATER IN M1503. THIS WAS FOUND WHILE ATTEMPTING TO DO A STREET LIGHT REPAIR ON ACCT# C3448. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE AND CAUSE OF THE SPILL IS UNKNOWN. THE STANDING WATER IN THE STRUCTURE HAD NO MOVEMENT, AND THE EXISTENCE OF ANY SEWER CONNECTIONS, SUMPS, OR DRAINS COULD NOT BE VERIFIED AT THIS TIME. ENV STOP TAG# 42737 WAS PLACED AND ONE LIQUID SAMPLE TAKEN ON E PRIORITY FOR PCB ANALYSIS ON CHAIN OF CUSTODY# EE05042. THE SAMPLE WILL BE TAKEN TO CHEM LAB BY MR SFERRAZZA AND CLEANUP IS PENDING LAB RESULTS. J ANDERSON UPDATE 1-10-06 16:00HRS LAB SEQ# 06-00240-001 FLASHPOINT >140 DEG F. S. PACE 49874. UPDATE 10-JAN-2006 20:24 HRS. LSN-06-00241-001 MATRIX : OIL GRAB. 1004 PPM C.HOGAN 07511 UPDATE 10-JAN-2006 20:43 HRS. LSN-06-00242-001 MATRIX : WATER & OIL GRAB ANALYSIS INDICATES A PRESENCE OF A CABLE OIL. C.HOGAN 07511 UPDATE 10-JAN-2006 11:21 HRS. DUE TO THE HIGH PCB COUNT (1004 PPM) INCIDENT# 162484 WILL NOT BE MEETING THE 72HR CLOCK AND WILL BE RECLASSIFIED AS SPILL OIL (UNKNOWN TYPE). C.HOGAN 07511 "

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site	Database(s)	EDR ID Number	EPA ID Number
------	-------------	---------------	---------------

Remarks: "1 GALL UNK OIL IN THE MANHOLE ON 20 GALS WATER-UNK REASON FOR SPILL-NO CONTACT-CLEANUP PENDING pcb COUNT-FURTHER EVAL OF HIGH pcb COUNT. 162484"

All Materials:

Site ID:	357925
Operable Unit ID:	1115191
Operable Unit:	01
Material ID:	2105248
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported